A DITT	TPM CIRCLE NO :- 3		ACTIVITY	KK	Q	M P	М .	JH	SHE	ОТ	DI	M   E&		1761		CHEET		
AD <b>y</b> IK	1 TPM CIRCLE NAME :		OSS NO. / STEP										] KAI/	IZEN	IUt#	A SHEET		
	DEPT :- Q.A		RESULT AREA	Р	Q		EF :- A	1	С	D	S				100			
CELL :- A242	CELL NAME:- Tensioner	MACH	IINE / STAGE :- CN	<u>C</u>						OPE	ERA	TION :	Borin	g				
<b>KAIZEN THEME -To avoid</b> A 242 Body Dia. 11.0 undersize. Spec 11.0 -0.1/-			IDEA :- Point to be added in TBM replacement sheet .  COUNTERMEASURE: 4) Poll corow & Poll BENCHMARK 14 No.															
0.118, Actual - 10.870.		_	COUNTERMEASURE:-1) Ball screw & Ball									GET	· ·		No.			
WIDELY/DEEPLY:-			nut replaced								KAIZEN START 19.01.2015							
DDODI EM / DD	ESENT STATUS - A 242	2) Po	oint to be adde	d in 1	ГВІ	<b>VI</b> re	plac	em	ent	K	(AIZ	EN FIN	ISH	0	3.02.01	L5		
Body Dia. 11.0		shee	t.													esh Padw alunj ,Nar		
														,		. ,,		
												BENEFITS:-						
													1. Prevent Re-occurrence of					
													Customer Complaint.					
										2	2.	Reduc	e COP	Q.				
											KAIZEN SUSTENANCE							
	BEFOR	RE						Α	FTE	<b>r</b>		_				dded in		
WHY - WHY AN	NI VOIC :	RESI	JLT :-					<u>'</u>				-		ent sh	eet .			
Why 1 - A 242 Body Dia. 11.0 undersize.		IKLO									HOW TO DO: Audit							
Willy 1 - A 242 DO	dy Dia. 11.0 ondersize.									F	RE	QUEN	<b>CY</b> :3	month	าร			
Why 2 – X axis rep (actual ob	peatability not ok oserved 0.08mm)		14															
Why 3 - Ball screv	v ,Nut wear out .																	
<b>Why 4</b> – Natural o	detoration										ER	IAL C		OUR C		ING KAI		
ROOT CAUSE-	Natural detoration						_					N RS		IN RS		IN RS		
REGISTRATION	NO. & DATE:- 23.01.20	15	Before			Till o	D tate		\$	SF	₹.  ,					DEPLOY		
REGISTERED B	Y :- Ganesh Padwalkar		Deloie			11111	1916			NC	<b>)</b>			1				
•		$\dashv$										N/	4					
WANAGER'S SI	GN :- Sunil kinkar	1								1	- 1			1				