	1										1						
A DVIIZ	D1E	TPM CIRCLE NO :- 01		ACTIVITY	KK	QM	PM	Jŀ	I SHE	ОТ	DM	E&T	VAI7EN	INE	A SHEET		
ADVIK <sup>1</sup>	F 13	TPM CIRCLE NAME: Achiev DEPT:-IQA	er LOSS NO. / STEP RESULT AREA	P	0	Α		С	D	S	М	<sub>i</sub> Nailen		JUEEI			
CELL:- A225	CELI	L NAME:- A225	MAC	HINE / STAGE :- Hobin		Ų	Α		<u> </u>	+-			Hobing				
KAIZEN THEME: To Eliminate rejection A225 Gear II			IDEA :- 1)Magnetic burr filter / collector provided on machine to filter the oil														
line mark on flanks																	
PROBLEM PRESENT STATUS :- A225 Gear II line			COUNTERMEASURE:-1)Magnetic burr filter / collector								BENCHMARK			63			
mark on flanks				provided on machine to filter the oil  2)Hob regrinding frequency decided after 800nos							TARGET			0			
											KAIZEN START			06.05.2			
				3)Hob shifting frequency decided after 25nos 4)Only coated hob will be used for operation							TDC KAIZEN FINISH			11.05.2			
Before				4)Only coated nob will be used for operation							KAIZEI	N FINIS	SH	11.05.2	016		
				After							TEAM MEMBERS: Dhananjay, Santosh, Sachin, Sangita BENEFITS:-						
											1) Avoid line mark rejection						
											1) Avoid fine mark rejection						
											KAIZEN SUSTENANCE						
WHY - WHY ANALYSIS :-				RESULT :-								WHAT TO DO:- Hob shifting  HOW TO DO:- Check visually.					
Why1 :- A225 Gear II line mark on flank Why2 :-Line mark generated because of burr found at Hob flank.				NESSET :													
Why4:-Burr collector not provided.				70 ¬ 63							TREQUERCEAILEI 23 NO S						
			60	-													
			50 - 40 -								SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT						
ROOT CAUSE: 1) B	Burr co	ollector not provided.	30	-							-	CELL	RESPONCIE	BILITY	STATUS		
			20	-							No						
REGISTRATION NO.	. & DA	TE: 06.05.2016	10 0				0					A225	Mr. Datta	a	Complet		
REGISTERED BY :	-IQA T	eam.		May-15	J	une 20	016 (T	ill 2	5.06)			Shaft drivin			ed		
MANAGER'S SIGN :	-Sand	ip Patil, Sunil kinkar									+						
													•				