TPM CIRCLE NO:- 3 **TPM CIRCLE NAME:** Oil Pump -1 **DEPT**:- Assembly

ACTIVITY LOSS NO. / STEP **RESULT AREA**

KK

Ρ

IDEA:- Gear to be modified for sensing R.P.M.

DEF :- A

PM

SHE OT С D

DM E&T

KAIZEN IDEA SHEET

CELL:-A247

CELL NAME:- A285 Assembly

MACHINE / STAGE :- A285 Assembly Line

COUNTERMEASURE:- Similar product

customer end gear is used with proper

OPERATION:- Free rotation Stage

KAIZEN THEME: To eliminate rejection of

rotation jam due to low R.P.M.

WIDELY/DEEPLY:-

PROBLEM / PRESENT STATUS :- 40 no's found having low R.P.M.



WHY - WHY ANALYSIS :-

Why1: Low R.P.M

flat







ROOT CAUSE: Gear teeth wear out.

Why 2: R.P.M not achieved as per spec.


Why 3:- Sensor not cut of gear teeth Why 4: Gear teeth wear out and gets

REGISTRATION NO. & DATE: 26.08.14

REGISTERED BY: - Bhavesh Pednekar

MANAGER'S SIGN :- Anil Shende

RESULT:-



BENCHMARK	40 No.
TARGET	0 No.
KAIZEN START	25.08.2014
KAIZEN FINISH	26.08.2014

TEAM MEMBERS :-
Bhavesh Pednekar
Sandeep Patil
BENEFITS:-

- 1. Prevent low R.P.M. problem
- 2. Reduce COPQ.

KAIZEN SUSTENANCE

WHAT TO DO: To check daily. **HOW TO DO:** Verify pokayoke at the start and hourly basis with master sample.

FREQUENCY: 100 %

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

	SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS
	01	A301	26.08.14	Prod.	С