

CELL :-A456 CELL NAME:-cobi Brake Assy MACHINE / STAGE:-Traceability process OPERATION :- Batch code marking

KAIZEN THEME :- To Avoid A456 Plate Traceability marking wrong direction.

IDEA :- Provided supporting block of plate in current process.

WIDELY/DEEPLY:-

COUNTERMEASURE:- Provided supporting block of plate in current process.


BENCHMARK	01 No.
TARGET	0 No.
KAIZEN START	15.05.15
KAIZEN FINISH	16.05.15

PROBLEM / PRESENT STATUS :-To Avoid A456 Plate Traceability marking wrong direction.

TEAM MEMBERS :-
Mr.Sachin & Mr.Manjunath



BEFORE



AFTER

BENEFITS :-

- 1) Reduce the cleaning time.
- 2) To avoid the wastage of ink.
- 3) Easily identified to traceability marking.

WHY - WHY ANALYSIS :-
 Why 1 : To Avoid A456 Plate Traceability marking wrong direction.
 Why 2 : There is no supporting block of plate in current process

RESULT :-

Process Improvements

KAIZEN SUSTENANCE

WHAT TO DO : Inadequate fixture.
HOW TO DO : Add to supporting plate on fixture.

FREQUENCY : Daily monitoring

ROOT CAUSE :-There is no supporting block of plate in current process

COST INCURRED FOR MAKING KAIZEN

MATERIAL COST IN RS	LABOUR COST IN RS	TOTAL COST IN RS
NA	NA	NA

REGISTRATION NO. & DATE:673 & 25.05.15

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

REGISTERED BY :- Mr.Sachin


SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS
1	A456	18.05.15	Sharath	Open

MANAGER'S SIGN :-Vijaykumar

Improvements : To Avoid Traceability marking wrong direction .

Before

After



- Inadequate fixture

Provided supporting plate
 Scope of Implementation: 1
 Completed:1
 Pending :0

CELL :- A456-II | CELL NAME:- CBS assembly | MACHINE / STAGE:- Hex-nut tightening | OPERATION :- 40

KAIZEN THEME :- to arrest arm comp lever inside bend

IDEA :- Make provision to Arrest Arm Comp Parking Lever Inside bend arrest at Process

WIDELY/DEEPLY:-

COUNTERMEASURE:- Implemented a Kaizen at Hexagonal-nut tightening stage, if any Arm comp lever Inside Bend at stage sub-assembly will not enter in fixture properly.



BENCHMARK	01 No.
TARGET	0 No.
KAIZEN START	18.06.15
KAIZEN FINISH	18.06.15

PROBLEM / PRESENT STATUS :-

Probability of Arm comp lever Inside Bend

TEAM MEMBERS :-

Mr, Dashrath-
Mr, Manjunath



BENEFITS :-

- 1) No Customer complaint,
- 2) Arrest Defect at primary stage,
- 3) Reduction Rework cost,

BEFORE

AFTER

KAIZEN SUSTENANCE

WHY - WHY ANALYSIS :-

Why 1 -Probability of Arm comp lever Inside Bend

Why 2 - No Provision to arrest defective arm comp lever from supplier end at process side

Why 3 - fixture design not considered to arrest Arm comp lever Inside Bend

WHAT TO DO : Check the fixture alignment


HOW TO DO : Re-tighten the Allen bolts with Allen keys

FREQUENCY : Twice a week.

Note :- upcoming hex-nut fixture design to be considered to arrest bent arm comp at process side.

ROOT CAUSE :- Weak fixture design.

RESULT :-



COST INCURRED FOR MAKING KAIZEN

MATERIAL COST IN RS	LABOUR COST IN RS	TOTAL COST IN RS
NA	NA	In-house

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS
1	A 456-1	20.06.15	Dashrath	Open.


REGISTRATION NO. & DATE: 705 & 18.06.15

REGISTERED BY :- Mr, Dashrath

MANAGER'S SIGN :- Mr, Vijay Kumar


Theme : To Arrest Arm-Comp Parking Lever inside Bend(Angle O/s).

Before



- 1) No provision to arrest Angle –Inside Bend.
- 2) In-adequate Fixture

After



- 1) Kaizen implemented at assembly process side,
- 2) Now the Arm Comp Parking lever arresting at sub assembly.

Defect:**Parking Lever Fowling with, Break Lever When Brake Apply**