**TPM CIRCLE NO :- 2 ACTIVITY** KK QM PM JH SHE KAIZEN IDEA SHEET **TPM CIRCLE NAME: Joshile** LOSS NO. / STEP **DEPT**:- Manufacturing Engg. **RESULT AREA** Ρ C DEF :- A **CELL NAME:- Drum Change Line** MACHINE / STAGE :- VMC/Machining **CELL:-A351 OPERATION**:-Operation No. 40 **KAIZEN THEME:** To Prevent defect of A351 **IDEA**:- Poka Yoke to be provide DGS at grooving stage. **BENCHMARK** 5 Nos **COUNTERMEASURE:-** Poka yoke provided by **TARGET** Zero

### WIDELY/DEEPLY:-

**PROBLEM / PRESENT STATUS :- A351 DGS** track damage due to wrong loading happening at grooving stage.



**BEFORE** 

#### WHY - WHY ANALYSIS :-

Why1: 05 Nos In-house rejection happened at grooving stage.

Why 2:- Component wrong loading.

Why 3:- Machine Not detected.

Why 4:- No Poka Yoke

**ROOT CAUSE: - No Poka Yoke** 

**REGISTRATION NO. & DATE: 1310,30.01.16** 

**REGISTERED BY :- Guru Basappa** 


MANAGER'S SIGN :- N.S.Pujari

adjusted the tail stock stroke length sensor & now machine will not start in component wrong loading.



**RESULT**:- Defect trend

# In-house rejection



**KAIZEN START** 16.01.2016 **KAIZEN FINISH** 17.01.2016

#### **TEAM MEMBERS:-**

N.S.Pujari, Mr. Pavan, Mr. Chethan.

#### **BENEFITS:-**

- 1.Prevent In-house rejection.
- 2. Prevent Ø7.1 EM tool breakage.
- 3. Prevent Ø4.1 locating pin breakage

#### **KAIZEN SUSTENANCE**

WHAT TO DO: Check Tail stock stroke length sensor correct position.

**HOW TO DO:** By component wrong

loading.

**AFTER** 

**FREQUENCY**: Once in a week.

## **COST INCURRED FOR MAKING KAIZEN**

MATERIAL COST IN RS	LABOUR COST IN RS	
IIN KS	IIV KS	IN RS

## SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

SR. NO.	CELL	TARGET	RESPONSIBILITY	STATU
1.				