CELL :A662 OBLINAME: OBJECTION AGE DESCRIPTION OBLINAME: OUNTERMENTITY There should be no play THE SHOULD START, 12/08/2019 TARGET DO: NAZEN START, 12/08/2019 TARGET DATE: 20/08/2019 TARGE	AD▼IK	TPM CIRCLE NO :- TPM CIRCLE NAME :		ACTIVITY LOSS NO./STE	KK	QM	PM	JH	SHE	ОТРМ	DM	E & T	KAIZEN IDEA				
KAIZEN THEME: TO Prevent the defect of A662 Filange Dia 15mm Unclean There should be no play There sho	PLANT:P14		Quality Assurance			Q	P	P, C	S	M, D	P, C	M	SHEET				
To Prevent the defect of A662 Flange Dia 15mm Unclean There should be no play There should be no play There should be no play TARGET:00 KAIZEN START:12/08/2019 TARGET DATE: 20/08/2019 TARGE	CELL :A662	CELL NAME :	A662 Flange ID 15mm boring MACHINE STAGE: CNC Turning								OPERATION: Boring			1			
There should be no play There should be no play TARGET-00 KAIZEN START: 12/00/2019 TARGET-00 KAIZEN START: 12/00/2019 TARGET ATE: 20/00/2019 TA	KAIZEN THEME :	KAIZEN IDEA :												E			
PROBLEM PRESENT STATUS COUNTERMEASURE: COUNTERMEASURE: COUNTERMEASURE: COUNTERMEASURE: COUNTERMEASURE: COUNTERMEASURE: COUNTERMEASURE: Reduced the clearance between part locating slot to locating Pin by increasing the locating pin width from 3.65mm to 3.80mm and Both locating Pins CD Defined 5.80 +/-0.05mm 2) Check Point to be add in fixture validation check sheet. WILY-WILY ANALYSIS: BEFORE AFTER ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar ANIZEN FINISH: 11/09/2-19 ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar ANIZEN FINISH: 11/09/2-19 ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar ANIZEN FINISH: 11/09/2-19 ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar ANIZEN FINISH: 11/09/2-19 ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar ANIZEN FINISH: 11/09/2-19 ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar ANIZEN FINISH: 11/09/2-19 ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar ANIZEN FINISH: 11/09/2-19 ILAM MEMBERS: Mr. Datta Proble* Mr. Manukar Mr. Datta Pr	To Prevent the defect of A662		BENCHMARK: 4500 nos.														
Reduced the clearance between part locating pin width observed 0.20(actual:-3.65mm) mm under size. Why 1: Naterial slot at one side. Why 3: The clearance between part locating pin width and CD not defined. ROD not defined. RESULTS: Rejection Trend	Flange Dia 15mm Unclean	There should b	TARGET:00														
Reduced the clearance between part locating slot to locating Pin by increasing the locating pin width from 3.65mm to 3.80mm and Both locating Pins CD Defined 5.80 +/-0.05mm 2)Check Point to be add in fixture validation check sheet. WHY-WHY ANALYSIS: BEFORE												KAIZEN START: 12/08/2019					
increasing the locating pin width from 3.65mm to 3.80mm and Both locating pins CD Defined 5.80 +/-0.05mm 2)Check Point to be add in fixture validation check sheet. WHY-WHY ANALYSIS: BEFORE AFTER TEAM MEMBERS: Mr. Datta-Pandre My 1: Material stock not available for boring at one side. Why 2: While loading part shifted at one side. Why 3: The clearance between part locating slot and locating pin was more 0.20mm. Why 4: Locating Pin width observed 0.20(actual:-3.65mm) mm under size. Why 5: Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not defined. RESULTS: Rejection Trend Locating Pin width and CD not de	PROBLEM PRESENT STATUS	COUNTERMEASURE:								TARGET DATE: 20/08/2019							
Why 1: Material stock not available for boring at one side. Why2: While loading part shifted at one side. Why3: The clearance between part locating slot and locating pin was more 0.20mm. Why4: Locating Pin width observed 0.20(actual:-3.65mm) mm under size. Why5: Locating Pin width and CD not defined. REGISTRATION NO.:P14/QM/2019/09 AREGISTRATION NO.:P14/QM/2019/09 AREGISTRATION NO.:P14/QM/2019/09 MANGERS SIGN: Mr. Manukar KAZIZEN SUSTAINACE WHA MANUKAT TO DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE added in DO: To revise the fixture drawing and check point for PE adde	800 no's A662 flange Dia 15mm bore unclean	increasing the locating pin width from 3.65mm to 3.80mm and Both locating Pins CD Defined 5.80 +/-0.05mm								KAIZEN FINISH: 11/09/2-19							
Mr. Datta-Pandre Mr. Manukar Why 1: Material stock not available for boring at one side. Why2: While loading part shifted at one side. Why3: The clearance between part locating slot and locating pin was more 0.20mm. Why4: Locating Pin width observed 0.20(actual:-3.65mm) mm under size. Why5: Locating Pin width and CD not defined. ROOT CAUSE: Locating Pin width and CD not defined. ROOT CAUSE: Locating Pin width and CD not defined. REGISTRATION NO:P14/QM/2019/09 SERIOL PAND FOR HORIZONTAL DEPLOYMENT Locating Pin width and CD not defined. 1000 800 1 A657 line 2 05/10/19 Madhu Inprocess HD SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT Locating Pin width and CD not defined. SERNO. PCELL/ PRODUCT TDC RESP. STATUS HD SCOPE INFORMATION IN OTHER PLANT HD SCOPE INFORMATION IN OTHER PLANT WHEN WHOM STATUS	WHY-WHY ANALYSIS:	BE	REFORE							EMBERS:							
WHAT TO DO: To revise the fixture drawing and check point for PE added in DDIS Why2: While loading part shifted at one side. Why3: The clearance between part locating slot and locating pin was more 0.20mm. Why4: Locating Pin width observed 0.20(actual:-3.65mm) mm under size. Why5: Locating Pin width and CD not defined. ROOT CAUSE:- Locating Pin width and CD not defined. RESULTS: Rejection Trend 800 800 800 800 1 A657 line 2 DS/10/19 Madhu Inprocess DATE: REGISTRATION NO:P14/QM/2019/09 500 HD SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT 1 A657 line 2 DS/10/19 Madhu Inprocess HD SCOPE INFORMATION IN OTHER PLANT SR.NO. PLANT WHEN WHOM STATUS									- 1			Mr. Manu	kar				
Locating Pin width and CD not defined. 1000 800 REGISTRATION NO.:P14/QM/2019/09 DATE: REGISTERED BY: Manash KP MANGERS SIGN: TDC RESP. STATUS 1 A657 line 2 05/10/19 Madhu Inprocess HD SCOPE INFORMATION IN OTHER PLANT SR.NO. PLANT WHEN WHOM STATUS	available for boring at one side. Why2: While loading part shifted at one side. Why3: The clearance between part locating slot and locating pin was more 0.20mm. Why4: Locating Pin width observed 0.20(actual:-3.65mm) mm under size. Why5: Locating Pin width and CD not defined.								WHAT T for PE ac HOW TO FREQUE	O DO: To r dded in DDI D DO:As per NCY: Each o	evise the f S revised d occurrence	rawing & I	DDIS				
defined. 1000 800 REGISTRATION NO.:P14/QM/2019/09 DATE: REGISTERED BY: Manash KP MANGERS SIGN: 1000 800 1 A657 line 2 05/10/19 Madhu Inprocess HD SCOPE INFORMATION IN OTHER PLANT SR.NO. PLANT WHEN WHOM STATUS		RESULTS: Rejection Tr	end						S	COPE & PLA	AN FOR HO	ORIZONTAI	L DEPLOYMENT				
REGISTRATION NO.:P14/QM/2019/09 DATE: REGISTERED BY: Manash KP MANGERS SIGN: 1 A657 line 2 05/10/19 Madhu Inprocess HD SCOPE INFORMATION IN OTHER PLANT SR.NO. PLANT WHEN WHOM STATUS	defined.			200					SR.NO.		r TDC	RESI	P. STATUS				
THE SCOPE INFORMATION IN OTHER PLANT MANGERS SIGN: THO SCOPE INFORMATION IN OTHER PLANT SR.NO. PLANT WHEN WHOM STATUS	REGISTRATION NO.:P14/QM/2019/09	-		RUU	Mil				1	A657 lin	e 2 05/10/1	9 Madl	hu Inprocess				
SR.NO. PLANT WHEN WHOM STATUS	DATE: REGISTERED BY: Manash KP	-				0			HD SCOPE INFORMATION IN OTHER PLANT								
	MANGERS SIGN:			Refore		Λftor			SR.NO.	PLANT	WHEN	WHOM	STATUS				

