TPM CIRCLE NO :-04		ACTIVITY	KK	QM	PM JI	H S	SHE	ОТ	DM	E&T				
ADVIK P1 TPM CIRCLE NAME : Oil put	mp	LOSS NO. / STEP				_		D		м	- Kaizi	en idea s	HEEI	
DEPT : Machine Shop           CELL :- A 410         CELL NAME: Oil Pump											 Machinin	σ		
KAIZEN THEME - : To Avoid Wrong Load.	IDEA : Provide Locating Pin.  COUNTERMEASURE Locating pin provided BENCHMARK 02													
WIDELY/DEEPLY:-	COUNTERMEASURE- Locating pin provided								TARGET 0					
PROBLEM / PRESENT STATUS :- During the		in fixture to Avoid Part Wrong Load.           AFTER							KAIZEN START         14.07.15           KAIZEN FINISH         16.07.15					
Loading of Part it Can be Wrong Load.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The second				ちゃん			Dilip P Nitin Nilesh	Phapa Sutai <u>n Kha</u> FITS :	r dke	g Load of P	art	
	iles bio							KAIZEN SUSTENANCE						
WHY - WHY ANALYSIS :- Why1:During the Loading of Part it Can be Wrong Load. Why2: Part Can Load Out Side of Fixture Pin. Why3: No Any Poka Yoke Available.	<ul> <li><b>RESULT</b> :-</li> <li>1) Part Wrong Loading Avoided.</li> <li>2) Rejection Due to Wrong Load Eliminated</li> </ul>								WHAT TO DO : Confirmation of availability of pin before loading part HOW TO DO : Daily Checking Start of Shift.					
ROOT CAUSE :- No Any Poka Yoke Available.								SC	OPE 8		N FOR HO		LOYMENT	
REGISTRATION NO. & DATE: - 20.07.2015								SF	- I CF		TARGET	RESPONSIBILIT	Y STATUS	
REGISTERED BY :- Umesh Pimple										<sup>t</sup> Set	20.9.15	NUTIN	Complet	
MANAGER'S SIGN :-Surendra Kulkarni.									I	Up	30.8.15	NITIN	e	