


ROOT CAUSE:-Gauge locating in top of the machine.

REGISTRATION NO. & DATE: 796 & 20.08.15.

REGISTERED BY :- Mr. Mallikarjuna

MANAGER'S SIGN:-



COST INCURRED FOR MAKING KAIZEN

MATERIAL COST	LABOUR COST	TOTAL COST
IN RS	IN RS	IN RS

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS