

KAIZEN THEME:- To Reduce the In-house Rejection

PROBLEM/PRESENT STATUS:-Body tapper after


Date punching & Batch code not clear due to its

**IDEA:-PCP Revised** 

# **COUNTERMEASURE:-**

**RESULT:-**

1) Pressure (2-5 bar) define in PCP



**BENCHMARK** 0 No. **TARGET** 0 No. 14.08.2017 KAIZEN START KAIZEN FINISH 17.08.2017

### **TEAM MEMBERS:-**

Rampal Sharma, Shailesh Sharma, Sanjeev

## **BENEFITS:-**

- 1)Quality improve
- 2) No Customer Complaint
- 3) Reduced Man power cost

#### **KAIZEN SUSTENANCE**

WHAT TO DO: Check point Added In

Process parameter

**HOW TO DO**: Check point for

Process sheet

**FREQUENCY**: Every shift

**BEFORE** 

Why Why Analysis Occurrence:-

Why 1 -Body Tapper

Clearance not ok

Pressure

not fix in

**PCP** 

Why 2 -Batch code punching pressure low or High

Why 3 - Pressure not define in PCP

## **ROOT CAUSE:-**


1) Pressure not define in PCP.

**REGISTRATION NO&DATE: -26/8/2017** 

**REGISTERED BY:-RAMPAL SHARMA** 

MANAGER'S SIGN :- Mr. VIKAS MISHRA





COST INCURRED FOR MAKING KAIZEN						
MATERIAL COST IN RS	LABOUR COST IN RS	TOTAL COST IN RS				

	SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT					
SR.	CELL	TARGET	RESPONSIBILITY	STATU		

1				
NO.	CELL	TARGET	RESPONSIBILITY	STATUS