15 - W	TPM CIRCLE NO :-		ACTIVITY	кк	QM	PM	JН	SHE	ОТРМ	DM	E & T		
AD ▼ IK	TPM CIRCLE NAME:		LOSS NO./STEP									KAIZEN IDEA	
	DEPT:	Production	RESULT AREA	С	Q	P	P, C	s	M, D	P, C	М	SHEET	
CELL :Oil Pump Cell	CELL NAME :	: Clearance testing MACHINE STAGE:						OPERATION:					
KAIZEN THEME :	KAIZEN IDEA :			<u> </u>		ļ				I .			
To detect the Dowel pin	Shaft Locating fixture hole to be provide.							BENCHMARK: 1					
missing								TARGET:		0			
								KAIZEN START: 20.10.2013					
PROBLEM PRESENT STATUS:	COUNTERMEASURE:							TARGET DATE: 24.10.2018					
Dowel pin missing issue found	Hole provided in Fixture. If Pin missing, Shaft will fall down and will be						KAIZEN FINISH: 27-10-2018						
	identified in Clearance stage itself.						TEAM MEMBERS:						
							Usha	Iannu		Operator Sr.Enginer-Production			
							Praveen Jannu Karthikeyan.S			AM - Quality.			
							BENEFITS:-						
							1.Productivity will be increased.						
							2.Rejection % will be Zero.						
WHY-WHY ANALYSIS:  Problem Description:- Dowel Pin	BEFORE AFTER						eo Clip	KAIZEN SUSTAINANCE WHAT TO DO:					
Problem Description:- Dowel Pin Missing  Why1:- Not detected during clearance teasting								To be updated in poka yoke verification sheet					
Why2:- No Poka yoke for Pin missing								ноw то ро: Daily poka yoke verification.					
	Fixture No through hole, No provision to escape roller miss shaft  Fixture through hole made, Provision to escape roller miss shaft						FREQUENCY: Daily						
ROOT CAUSE:-	RESULTS:	RESULTS:						SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT					
No Poka yoke for Pin missing								SR.NO.	CELL/	TDC	RESP.	STATUS	
	l 🗖 .								PRODUCT NA				
							_		INA				
		_						1	1		ļ		
		1											
		1					_		HD SCOPE INF	FORMATION I	N OTHER PLAN	Т	
REGISTRATION NO.:P14/2018/OM/066		1			0		_		HD SCOPE INF	FORMATION II	N OTHER PLAN		
REGISTRATION NO.:P14/2018/QM/066 DATE:22.11.2018		1			0		_	SR.NO.	1	4		T STATUS	
				A			<b>-</b>		PLANT	4			
DATE:22.11.2018		Before		A	0 fter		_		PLANT	4			