| ADV IK | Quality Improvement Kaizen | | | | | | | | | | | | | | P14 | | | | |
|--|---|--|--|----------------|------------------------------|-------------|----|-----|---------------------------------|---------------------------------|--|-----------------------------|---------------------|--------------|--------|--|--|----------------------------|--|
| K2 TPM CIRCLE NO: 2 TPM CIRCLE NAME: Joshile DEPT: Manufacturing Enginee | | | ACTIVITY | КК | QM | PM | JH | SHE | ОТ | DM E8 | &Т | KA17 | EN INF | | | | | | |
| | | ring | LOSS NO. / STEP RESULT AREA | Р | 0 | | | 6 | <u> </u> | | м | | | | | | | | |
| CELL: A128 | DEPT: Manufacturing Enginee CELL NAME: Tensioner Assy. | | INE / STAGE: Pneumat | - | <u>Q</u> ς/Δςςa | | | C | D | | | | F/IMS/05 Marking | | | | | | |
| KAIZEN THEME: To Prevent May Happen Customer Complaint of A128 Tensioner Assy. | | | | | | | | | | | | | | | | | | | |
| WIDELY/DEEPLY: | | IDEA: Poka Yoke to be provide | | | | | | | | | | | | | | | | | |
| PRESENT STATUS : May chance of customer complaint due to wrong location of traceability | | | BENCHMARK 01 Nos | | | | | | | | s | | | | | | | | |
| | | | COUNTERMEASURE : Provided poke yoke to | | | | | | | | | Zero | | | | | | | |
| | | | prevent possibility of component wrong KAIZEN STA | | | | | | | | | | 01.05.17 | | | | | | |
| marking . | | loading & wrong location of traceability | | | | | | | | | KAIZEN FINISH 15.05.17 | | | | | | | | |
| Comp. Locate on Fix. In reverse direction | | | | | | | | | | | | TEAM MEMBERS: N.S.Pujari | | | | | | | |
| | | | marking . Poka Yoke Pin | | | | | | | | | | | | | | | | |
| | | | 1 and 1 | - | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | BENEFITS: | | | | | | | |
| | | | | | | | | | | | 1) Prevent May happen customer complaint | | | | | | | | |
| | | | | | | | | | | | | | | | | | | Comp. Not Locating Fix. | |
| | | | 1 | | | | | | | | | | | | | | | | |
| | | | WHY - WHY ANALYSIS :- | | RESULT:- May happen Customer | | | | | | | | KAIZEN SUSTENANCE | | | | | | |
| | | | Why1: May chance of customer complaint due to wrong location traceability marking. Why2:Posibility of component wrong loading in traceability marking fixture. Why3: Poka Yoke is Not there. | | | 2 Complaint | | | | | | | | | | | | | |
| WHAT TO DO : Poke Yoke to be add in check | | | | | | | | | | | | | | | | | | | |
| list & verify | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | HOW TO DO : By wrong loading of | | | | | | | | | | |
| 1 - component | | | | | | | | | | | | | | | | | | | |
| FR | | | | | | | | | FREQUENCY : Once in a Day. | | | | | | | | | | |
| | | | | | | | | | | COST INCURRED FOR MAKING KAIZEN | | | | | | | | | |
| | | | | | | | | | MA | | | | | | L COST | | | | |
| | | | | | | | | | | | | | NRS IN RS | | | | | | |
| ROOT CAUSE:- Poka Yoke is Not there. | | | | | | | |] | | | | | | | | | | | |
| | | 0 + | Before | After | | | | | SCOPE 8 | E & PLAN FOR HORIZONTAL D | | | | | | | | | |
| REGISTRATION NO. | & DATE: 1662 & 31.05.2017 | | Deloie | | Prevent May happen | | | | | SR. CELL TARGET | | | | RESP. STATUS | | | | | |
| REGISTERED BY: Nig | | | y luck there is No ustomer complaint | | customer con | | | | NC | | | ANGEI | RESP | • | STATUS | | | | |
| <u> </u> | | C | | by improvement | | | | 1 | A128 L1 A157 | _ _ | 0.06.17 | N.S.Pu | jari | Open | | | | | |
| MANAGER'S SIGN: Mr. N.S.Pujari | | | | | | | | | | A157 | | | | | | | | | |