


## **Process Side Improvement**

**Problem Description 1** :- Daily segrigation of rotor in model wise due to Rotor miss from bins and collected in coolant tank .



Why Why Analysis :-

Why 1 – Daily segrigation of rotor in model wise due to Rotor miss from bins and collected in coolant tank .

Why 2 – It happened during lift of bins in machine.

Why 3 – Improper handling of bins after grinding.

**Root Cause :**– Improper handling of bins after grinding.

Kaizen Idea :- Provide meshed sheet box

Countermeasure - Provide meshed sheet box to collect all rotor inside box.

