## **Defect Elimination**

## **PROD**

204

17-Nov-14

| ADVIV                             | TPM (               | Circle No.: | Activity              | KK                | JH | QM  | PM | SHE                   | OT | DM            | E&T | WAIZEN IDEA CHEET |  |
|-----------------------------------|---------------------|-------------|-----------------------|-------------------|----|-----|----|-----------------------|----|---------------|-----|-------------------|--|
| <b>ADVIK</b>                      | TPM Circle Name:    |             | Loss no.              |                   | 4  | 1   |    | 3 V                   |    |               |     | KAIZEN IDEA SHEET |  |
| Plant-1                           |                     |             | Step                  |                   |    |     |    | 3 V                   |    |               |     |                   |  |
| Chakan                            | Dept.: Machine Shop |             | Result Area           | P Q-Def. A / B /C |    | C D | D  | S                     | M  | Kaizen No.: 3 |     |                   |  |
| Cell No.:A347 Cell Name: Oil Pump |                     | 28 100      | Process / Stage : VMC |                   |    |     |    | Operation : Machining |    |               |     |                   |  |

Kaizen Theme:

To Avoid Backface chatter mark.

Idea: To Design standard Tool.

Counter Measure: Insert Type Spot Face Cutter Design for Back Facing Operation.

## Problem / Present Status:

A347 cover Backface chatter mark Problem.



Before :



Kaizen Finish 5-Dec-14 Team Members With Sign:

Rejection Eliminate.

Benefits:

Kaizen Sustenance:

1.Umesh Pimple

2. Ritesh Bhole.

Bench Mark

Target Kaizen Start

P

C

D

S

M

3. Navnath Karanikhile.

## Why Why Analysis:

facing.

Why 1: A347 cover Backface chatter mark.

Why 2: Machining not Properly.

Why 3:Used / Breakage tool using for back facing.

Why 4:No standard tool Available for back facing Operation.



How to do: Tool Life Monitoring.

Root Cause : - No standard tool Available for back Result :1) Rejection Eliminate due of Chatter mark on Back Face.

What to do: Use Only Standard Tool.

| Registration no.& dt :15/10/14     |  |
|------------------------------------|--|
| Submitted by: Umesh Pimple         |  |
| Manager's Sign : Surendra Kulkarni |  |

| Scope & Plan for Horizontal Deployment |                                       |                |                    |           |  |  |  |
|--|---------------------------------------|----------------|--------------------|-----------|--|--|--|
| Sr.                                    | Model                                 | Target<br>Date | Responsi<br>bility | Status    |  |  |  |
| 1                                      | Using on all<br>Backface<br>operation | 15.02.15       | Umesh              | Inprocess |  |  |  |