<b>ADV</b> IK	VIK Working Environment Improvement Kaizen																P14					
		TPM CIRCLE N			ACTI			KK	QM	P	M	JH	SHE	ОТ	DM	E&T	K٨	17EN	i ide	V CL	JEET	٦
		TPM CIRCLE NAME:			LOSS NO. / STEP												11/1					
	DEPT: Production				RESULTAREA P Q DEF: A C								D S M F/IMS/0 OPERATION: Grouping.									
CELL: A128 Line 2 CELL NAME: Tensioner														OPE	:KAII			_				
KAIZEN THEME: To	o impro	t@Gr	@ Grouping stage.																			
WIDELY/DEEPLY:					IDEA: Grouping activity should be auto.																	
PRESENT STATUS: Operator feels				COL	<b>COUNTERMEASURE</b> : Changed Grouping station										BENCHMARK							_
uncomfortable to operate @ grouping stage.															TARGET							_
andermontable to operate te Brouping staget					from manual operating to auto operating to										KAIZEN START 15.02.17   KAIZEN FINISU 22.02.17							_
			improve ergonomics activity.										K	KAIZEN FINISH 22.02.17					1/		_	
															TEAM MEMBERS: Mr. N.S.Pujari.							
												1	<ul><li>BENEFITS:</li><li>1. User friendly.</li><li>2. Ergonomics activity reduced.</li></ul>									
												KAIZEN SUSTENANCE										
BEFORE				AFTER									RV	WHAT TO DO : Ir reversible Kaizen								
														HOW TO DO :								
WHY - WHY ANALYSIS :-				RESULT:- :-									F	<b>FREQUENCY</b> : One time action.								
Why1: Operator feels uncomfortable to																						
operate @ grouping stage.																						
Why2: Grouping a	activity	is manual.																				
														C	COST INCURRED FOR MAKING KAIZEN							
												1		MA	TERIA	L COS	T LAE	BOUR (	COST	ΤΟΤΑΙ	L COST	1
ROOT CAUSE:- Grouping activity is manual.													IN RS IN RS				IN	RS				
NOOT CROSE GIU	whing	activity is in	undun.		/										NR 20	000/-				INR 2	20000/-	
															SCOPE & PLAN FOR HORIZONTAL DEPLOYME							
REGISTRATION NO. & DATE: 1501 & 25.02.17														SF	SR. CELL TARGET RECR						STATU	_
REGISTERED BY: Mr. Guru Bassappa				Ergonomics activity is Ergonomics activity										NC								-
MANAGER'S SIGN: Mr. Chamaraj				more. is less.										No Scope in P14								