
TPM CIRCLE NO :-	ACTIVITY	KK	QM	PM JH	SHE	ОТ	DM	E&1	KAIZEN IDEA SHEET
TPM CIRCLE NAME :	LOSS NO. / STEP								KAIZEN NO:-
DEPT :- Quality	RESULT AREA	P Q DEF:-A/B/C C		:   C	D S		М		
CELL : CELL NAME:- DGS M	ACHINE / STAGE:- Kashi (DGS	CHINE / STAGE:- Kashi (DGS Grinding)					OPERATION :- Grinding		
KAIZEN THEME :- To reduce the casting Grooving Flash outflow from supplier.	IDEA: Increase Awareness  COUNTERMEASURE: By providing training & Displaying limit sample at supplier end to reduce						BENCHMARK 10 Nos. TARGET Zero KAIZEN START 24.05.2016		
WIDELY/DEEPLY:-	Outflow from Kashi End to Advik End.							NISH 24.05.2016	
PROBLEM / PRESENT STATUS:- During Incoming inspection at inward stage Casting grooving flash observed in Drum Change (A189).  N.A.	CK OF THE STATE OF		•	h		T F	EAM Rajes BENE	FITS	MBERS :-Sumit Kumar, umar  S:- Operator moral boost umprove  IZEN SUSTENANCE
WHY WHY ANALYSIS:- WHY 1:- Grooving flash observed in DGS (A189) at Advik Inward Stage. WHY 2:- Grooving flash part skip form supplier Inspection stage WHY 3:Operator not aware about this Grooving flash	RESULT:- Grooving flareduced.	sh pr	obler		NFTE OW	\ - -	WOH	ТО	DDO :- Reversible DO :- Monitoring NCY :- Daily check
							ОСТ	INIOI	LIDDED FOR MAKING KAIZE

**ROOT CAUSE:-** Lack of Awareness

**REGISTRATION NO&DATE:** 

**REGISTERED BY: - Sumit Kumar** 

MANAGER'S SIGN:-



## COST INCURRED FOR MAKING KAIZEN

MATERIAL COST	LABOUR COST	TOTAL COST		
RS.	RS.	RS.		
N.A				

## SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS
-	N.A	N.A		