## Shop: ASSEMBLY SHOP

## **Date of Implementation:** 19/07/14

Machine / Location : A328/A372 Oil pump Assembly

	<i>.</i>
Before	After
<ol> <li>Clearance Checking With shaft &amp; plate sub assly. (First operator)– 20 sec</li> </ol>	<ol> <li>Clearance Checking With shaft &amp; plate sub assly. (First operator)– 20 sec</li> </ol>
<ol> <li>Hex bolt fitment Gear insertion in shaft (Second operator) – 20 Sec</li> </ol>	<ol> <li>Hex bolt fitment Gear insertion in shaft (Second operator) – 20 Sec</li> </ol>
3. Pin insertion, Circlip fitment & free rotation (Third operator) - 16	3. Pin insertion, Circlip fitment & Auto free rotation & flushing (Third operator) – 24
4. Inspection – 16 Sec	4. Inspection & Packing – 23 Sec
5. Flushing & Packing – 18 Sec.	
Problem/Present Status : Used 5 man power for total assembly of A328/A372 oil pump	Countermeasure : Used 4 manpower for total assembly Of A328/A372 oil pump.
<b>Cycle time</b> – 20 sec. <b>Out put per man</b> – 294 Nos.	Cycle time – 24 sec. Out put per man – 306 Nos. Benefit : increase in output per man by 12 nos. (4%)

PRODN