Quality Improvement

KK

Р

QM

PM

DEF :- A

P14

K3

WIDELY/DEEPLY:

CELL:- A467

TPM CIRCLE NAME:

PRESENT STATUS: - Without plug job pressing

happening & load confirmation getting ok.

KAIZEN THEME: - Quality Improvement

DEPT: Maintenance **CELL NAME:-** Tensioner

TPM CIRCLE NO:

MACHINE / STAGE:- Plug pressing

BEFORE


IDEA:- Poka yoke

ACTIVITY

LOSS NO. / STEP

RESULT AREA

COUNTERMEASURE :- Provided a photo



RESULT:- Plug missing operation eliminated

SHE

C

DM

S

М

BENCHMARK

KAIZEN START KAIZEN FINISH

TARGET

OPERATION: -Plug pressing

OT

Siddappa **BENEFITS:-**

TEAM MEMBERS:-Manjunath HS

1. Chance of plug missing eliminated.

KAIZEN SUSTENANCE

WHAT TO DO:- To be add in Pokamoke

F/IMS/05

5 no's

12.02.2017

12.02.2017

WHY - WHY ANALYSIS :-

Why1:- Chance of customer complaint Why2:- Process getting on without plug

Why3:- No detection of plug missing Why4:- No pokayoke

6 5 5 4

0

3 2 1

MATERIAL COST IN RS

list

NO.

COST INCURRED FOR MAKING KAIZEN LABOUR COST **TOTAL COST IN RS**

HOW TO DO: Manual verification

FREQUENCY: Daily

2050

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

IN RS

2050

STATUS

TARGET CELL RESP.

ROOT CAUSE:- No poka yoke

REGISTRATION NO. & DATE:1493 & 12.02.2017 REGISTERED BY:- Guru Basappa

MANAGER'S SIGN:- Dinesha m

Before

After

0