A DUITZ	TPM CIRCLE NO :-		ACTIVITY	KK	QM	PM .	IH :	SHE	ОТ	DM	E&T	<b>I K A 17</b>			CT	
ADVIK <sup>P14</sup>	TPM CIRCLE NAME :		LOSS NO. / STEP									KAIZEN IDEA SHEE			<u> </u>	
	DEPT :- Assembly shop	RESULT AREA		<b>P</b>   Q		DEF:-A		С	D	S	М	DI) (ET)	F/IMS/05			
CELL :- A247 CELI	L NAME:- CBS ASSY		INE / STAGE :- Rive								ON :	- RIVETI	NG			
<b>KAIZEN THEME :-</b> To Reduce the fixture PM time In A247 CBS line at riveting stage.		IDEA :- Auto provision to be provide for fixture clear								BENCHMARK 40						
			COUNTERMEASURE:- Provided air blower, after							TARGET 15						
WIDELY/DEEPLY:-		unload the component from fixture by logic								<b>KAIZEN START</b> 15.12.15				2.15		
PROBLEM / PRESENT STATUS :- Takes more		system air blower work automatically & clean								<b>KAIZEN FINISH</b> 18.12.15						
time for riveting fixture PM due to small chips accumulating in fixture & there is no any auto provision for fixture cleaning.		the fixture.								TEAM MEMBERS :- Shanth kumar.r Mr.Mahesh.N						
NO auto Provision for cleaning			Provided air blower for auto cleaning							BENEFITS: 1) Reduced Fixture time 40 min to 15 min. 2)Killed HTA area by action. 3)Work standardization. 4)Reduced Operator fatigue.  KAIZEN SUSTENANCE						
WHY - WHY ANALYSIS :-		RESUL	RESULT : Reduced fixture time.							WHAT TO DO: Check the presence of air blower & working condition. HOW TO DO: Visually						
Why1: Takes more time for riveting fixture										FREQUENCY : Once in a day.						
PM.		Fixture PM Time										• • • • • • • • • • • • • • • • • • • •				
<ul><li>Why2: After completion of riveting operation small chips accumulating in fixture.</li><li>Why3: No auto provision for fixture cleaning.</li></ul>		50 40 30							С	COST INCURRED FOR MAKING KAIZEN						
<b>ROOT CAUSE</b> :- No auto provision for fixture cleaning.		20 - 10 -					MA	IN RS IN RS IN				TOTAL CO IN RS 500	<u> </u>			
									SC.	SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT						
<b>REGISTRATION NO. &amp; DATE : 953 &amp;</b> 23.12.15			0							SR. CELL TARCET DESPONSIBILITY STATUS						
REGISTERED BY :-		Before After NO. CELL TARGET RE							KESPUN	-SPONZIBILIT (121A102						
MANAGER'S SIGN :-																
IVIAINAULI J JIUIN ."																