	TPM CIRCLE NO :-02	ACTIVITY			KK	QM	PM	JH	SHE	ОТ	DM	E&T	1/A					
	TPM CIRCLE NAME :-Innovation		LOSS NO. / STEP		IXIX	CIVI	1 171	311	JIIL		DIVI	Lai			ASHEEI			
	DEPT :-QA		RESULT AREA		P Q DEF:-		DEF :- B		С	D	S M (AIZEN NO:-							
CELL: - Drum change	CELL NAME:- Drum change	MACHINE / STAGE:- Center facing									OPERATION:- Center facing							
KAIZEN THEME: To eliminate the possibility of wrong side component loading during center facing.		IDEA:-Poka-Yoke																
		COUNTERMEASURE:- Provide a mechanical stopper at center									BENCHMARK 35 No's TARGET 0 No's							
WIDELY/DEEPLY:-			facing fixture for prevention of wrong loading of drum change									TARGET 0 No's KAIZEN START 23.07.15						
<u>'</u>			model A352. (If the operator load the component from wrong									KAIZEN STAKT 25.07.15 KAIZEN FINISH 28.08.15						
PROBLEM / PRESENT STATUS :- During component(DC			side then part will not rest in the fixture)									20.00.10						
A352) loading on center facing M/C part load in												TEAM MEMBERS :-						
wrong side.			8.0 tion									Rajesh Kumar,						
Stopper Stopper Stopper Sap should be less then 3.4 mm when part load in OK condition			for n of Gap more then 8.0 mm when part load in not OK condition								BENEFITS :-							
											Reduce the cost of poor quality. Increase the RFT.							
			Stopper for wrong loading wrong loading words. We stopper for wrong loading wrong wro								KAIZEN SUSTENANCE							
											WHAT TO DO:- Checking with part By part sit in wrong position. HOW TO DO:- Check point to be add							
WHY 1:- Possibility of wrong side component loading during center facing.		NESOLI OFIGER FIOCESS								- I.,								
													onitoring check sheet.					
Why 2:- Part not locate with specified slot.			40															
Why 3:- Poka			40 ₃₅ -	35						FI	FREQUENCY: Daily				•			
		l 8	30 -															
		Rej. Qty. in No's	25 -								COST INCURRED FOR MAKING KAIZEN							
			20 - 15 -		Under mor			nitoring			MATERIAL COST RS.		LABOUR COST RS.		TOTAL RS			
ROOT CAUSE:- Poka		Rej	10 -								350		50		400			
			5 -			0			SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT				MENT					
REGISTRATION NO&DATE: 23.0615			U +	Before	Af			fter		SR		T T		RESPONSIBILIT				
REGISTERED BY :-Rajesh Kumar										NC).							
		1								I 1								

MANAGER'S SIGN :-