Quality Improvement Kaizen

P14

	TPIVI CIRCLE NO:		ACTIVITY	KK	QIVI	PIVI	JH	SHE	5	ואוט	E&I	J W A IZENI INE A CHEET I
	TPM CIRCLE NAME:		LOSS NO. / STEP									KAIZEN IDEA SHEET
	DEPT: Production		RESULT AREA	P	Q	DEF :- F	١	С	D	S	М	F/IMS/05
CELL: A128 /A467	CELL NAME: Tensioner	MACH	HINE / STAGE: MTR 15E						OPERATION: Thread rolling			

KAIZEN THEME: To Eliminate defect @ thread rolling stage.

WIDELY/DEEPLY:

PRESENT STATUS: 40 No's A467 screw rejected due to face damage during threading operation.






BEFORE

IDEA: Stopper movement should not get disturb.

COUNTERMEASURE: Provided a slot in the stopper & locked with a fastener, where stopper movement will

be stationary to avoid face damage of the component.



TEAM MEMBERS:

Mr. Mallikarjuna Mr. Sridhar

BENEFITS:

MATERIAL COST

IN RS

INR 30/-

- 1. Rejection eliminated.
- 2. Operator moral increased.

KAIZEN SUSTENANCE

AFTER

WHAT TO DO: Ir reversible Kaizen. HOW TO DO: ----

FREQUENCY: One time action.

WHY - WHY ANALYSIS :-

Why1: 40 No's A467 screw rejected due to face damage during threading operation.

Why2: Screw face hits the roller face & gets damage.

Why3: Stopper movement gets disturb frequently.


ROOT CAUSE:- Stopper movement gets disturb frequently.

REGISTRATION NO. & DATE: 1449 & 20.01.17

REGISTERED BY: Mr. Guru Bassappa MANAGER'S SIGN: Mr. Chamaraj

0 No's

50



RESULT:-: Rejection reduced from 40 No's to

40

COST INCURRED FOR MAKING KAIZEN LABOUR COST

IN RS

TOTAL COST

IN RS

INR 30/-

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

TARGET RESP. CELL **STATUS**

No Scope in P14