ADVIK TPM CIRCLE NO :- TPM CIRCLE NAME : DEPT :- Maint.	LC	CTIVITY OSS NO. / STEP ESULT AREA	KK QM	PM JI		OT D	DM S	E&T M	KAIZEN I	NZEN IDEA	SHEET	
CELL:- CELL NAME: MA KAIZEN THEME:-To increase lux level	IDEA :-Provide light on machine											
quality WIDELY/DEEPLY:- PROBLEM / PRESENT STATUS :- Before Condition operator component quality check Problem due to less visualization ,No proper Visibility on component washing	Machine After ligh	COUNTERMEASURE:- Now Component washing Machine provided High quality lux label led light. After light installation component clear visibility and Also lux label improved.				9 <u>T.</u> K nd <u>K</u> T	KAIZEN START 28.11.2017					
WHY WHY ANALYSIS :- WHY :-Component washing light vision low WHY :-Light not available	780 730	Checking in lux label. 30					WHAT TO DO :- ЗУПОСТВИТЕЙНИИ ТО DO :- FREQUENCY :- COST INCURRED FOR MAKING KAIZEN MATERIAL COST LABOUR COST TOTAL COST					
ROOT CAUSE :-Light not available REGISTRATION NO&DATE: REGISTERED BY :-	680 630 580	750		650			SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT SR. NO. CELL TARGET RESPONSIBILITY STATUS					
MANAGER'S SIGN :-		Before		After								