	TPM CIRCLE NO :- 3	ACTIVITY	KK	(QM PN	л I .	ΙН	SHF	ОТ	וח	и Е&	τl					
ADVIK P1	TPM CIRCLE NAME :	LOSS NO. / STEP	IXIX	Ť	QIVI PIV	+ 31	-	SIIL		 	1 201	`	KA17F	N INFA	A SHEET		
AD III	DEPT :- Q.A	RESULT AREA	Р		Q DE	F :- A	\	С	D	s	М	П		אשו ווו.	JULLI		
CELL :- A215 CEL	L NAME:- Drum change	MACHINE / STAGE :- Pres	SS						OPE	ERA	TION	: P	ressing				
KAIZEN THEME -To avoid A 215 Drum change Pin Damage		IDEA :- Fixture to be modified.															
3 3 3 3	9 -	COUNTERMEASUR	F·-1)	F	ixture	to	he		Е	BEN	СНМА	ARK		4 No.			
WIDELY/DEEPLY:-		modified. 2) Currently marking on fixture								TARGET				0 No.			
WIDELI/DEEFLI		to locate part in correct direction 3) work									KAIZEN START KAIZEN FINISH				015		
PROBLEM / PRESI Drum change Pin	ENT STATUS - A 215 Damage	instruction displaye		ui	rectio	11 ,	3) V	VOIR					BERS	:-			
														ır ,vijay w	valuni.		
			Someshwar Salunke.														
									E	3EN	NEFIT	ΓS	-				
											 Prevent Re-occurrence of Customer Complaint. Reduce COPQ. 						
	The second								2	2.	Redu	ce (COPQ.				
									KAIZEN GUGTENANCE								
									KAIZEN SUSTENANCE								
	AFT							Γ	WHAT TO DO- NA								
WHY - WHY ANAL) Why 1 - A 215 Drum	RESULT :-								FREQUENCY : NA								
Why 2 - Pressing Don	e at the edge of Pin.																
Why 3 - Part not Loca	ate on its Location.																
Why 4 - No standard														ING KAI			
									MAT			30		_	TAL COST		
	1	<u> </u>	IN RS IN RS IN RS														
ROOT CAUSE- No s	standard pin pressing fixture											-					
DECICED ATION NO	O DATE: 00.04.004							S	-	5 1		_			DEPLOY		
	O. & DATE:- 28.01.2015								N(CELL	TΑ	RGER	SPONSIE	BILITETTATU		
	- Ganesh Padwalkar																
MANAGER'S SIGN	:- Sunil kinkar																

•