		TPM CIRCLE NO :-		ACTIVITY	КК	QM	PM	JH	SHE	ОТРМ	DM	E & T		
A	<b>DI</b> K	TPM CIRCLE NAME :		LOSS NO./STEP									KAIZEN IDEA	
Pla	nt : P14	DEPT :	Maintenance	RESULT AREA	С	Q	Ρ	Р, С	S	M, D	Р, С	м	SHEET	
CELL :	Utility	CELL NAME :	Utility	M/C STAGE:	Bore well				<b>OPERATION:</b>			Bore well		
KAIZEN THEME :		KAIZEN IDEA :								BENCHMARK:			01 Nos	
To measure the water consumption.		Provision of water meter.								TARGET:			00 no's	
									KAIZEN START:			20.02.2018		
									TARGET DATE:			25.02.2018		
PROBLEM PRESENT STATUS :		COUNTERMEASURE:							KAIZEN FINISH:			28.02.2018		
No tracking of water consumption.		Installed a water meter at bore well									Ganesh			
										Pawan				
										NS Puja	ri			
WHY-WHY ANALYSIS:		BEFORE			AFTER				BENEFITS:-					
Why1: - No tracking of water consumption. Why2:- No measuring unit .						0~			2. S	upport	to envi	ronmen	onitoring. t	
								KAIZEN SUSTAINANCE						
								Monitoring						
								HOW TO DO:						
								Safety Poka Yoke check sheet						
									FREQUENCY:					
								Monthly						
ROOT CAUSE									AN FOR HORIZONTAL					
									DEPLOYMENT					
No measurement					SR.		CE PROI	LL/ DUCT	т	DC	RI	SP.	STATUS	
					0	1	A1	.57					Completed	
REGISTRATION NO.:	P14/PM/2018/026													
DATE:	10.03.2018	_												
REGISTERED BY:	Mr. Nigama	No tracking Tracking				HD SCOPE INFO				ORMATION IN C			PLANT	
MANGERS SIGN:	Mr. Dinesha M	Before After			SR.	No	PI	ant	\ <b>\</b> /	HEN	\\/H	юм	STATUS	
													517105	
	0/F Day No 202 Days Date				1									

AHPL/QMS/FR/09/E, Rev. No.:03, Rev. Date:23.01.2018