AD V IK	TPM Circle No.:	Activity	KK	K JH	QM PM	A SHE	ОТ	DM	E&T	KAIZE	N IDEA S	3HEET	
	TPM Circle Name:	Loss no. Step								Kaizen No.: 03			
	Dept: ASSY.	Result Area	Р	0- Г	0ef. A / B /0	C	D	S	М	Naizen I			
Cell No.: A294 Gear shifter assy.		Kesun Area		-	stage : Assl		D	Б		Operation :	Rivetting		
		T 1 1							Operation : Rivetting.				
Kaizen Theme : To eliminate rejection of improper rivetting.		Idea : To avoid	Idea : To avoid customer complaints										
		Counter Measure : Fixture guide pin height increased.						Bene	ch Mark				
Problem / Present Status: 1.Rivetting dimension 0.50 mm not ok found.		Before : 1.Guide pin height not adequate to hold bracket						Targ	get			0	
								Kaiz	zen Start		2-Apr-14		
2. Firm rivetting not found.								Kaiz	zen Finisl	ı	22-Apr-14		
									Team Members With Sign : 1.Sandeep Jadhav 2.Samadhan Visave				
Why Why Analysis :	After :						Benefits						
1.Gear shifter assy. bracket rivet missing 2.Bracket riveting improper/loose		1.Preventive type po	1. Preventive type pokayoke implemented:						P				
		Existing fixture pin height increased by 4 mm to avoid tilting of bracket .							Q				
		2.Pin height checking started on weekly basis3.FGCP revised frequency from 1pc/hr to 100 % visual checking .											
3.During rivetting bracket tilt & fall down below		4. After rivetting height 0.50 mm SPC study conducted .						С	С				
		5.Bracket resting fixture two guide pin to be provide to eliminate tilting issue .							D				
4.Fixture guide pin height less.								S	S				
5.Weak fixture design.								Μ	М				
								111	Kaizen Sustenance :				
								Wh	What to do : Guide pin height checking on				
									monthly once.				
									-				
	Hoy							How to do : FGCP checkpoint added for rivetting vi					
Root Cause :		Result :											
		Customer complaint for rivet missing chances eliminated.						Scope & Plan for Horizontal Deployment					
		1.2											
Weak fixture design.	Neak fixture design.				1			Sr	Model	Target	Responsibility	Status	
								no		Dt	1 5		
		0.8 -							<u> </u>				
Registration no.& dt :		0.6 -											
		0.4 -							1.005				
Submited by : Sandeep Jadhav		0.2 -						1	A338	22.04.2014	Samadhan	Completed.	
Manager's Sign :		0 +											