											AH	PL/QM	IS/FR/	09/E		
A DOUBLE	TPM CIRCLE NO: 01	ACTIVITY	KK	QM	PM	JH	SHE	ОТ	DM	E&T	VAI7E	מו וג'		JCCT		
	TPM CIRCLE NAME :QM	LOSS NO. / STEP										ועו א.		100 I		
	DEPT: PRDN	RESULT AREA	Р	Q		F :- A	С	D	S	М						
CELL: A533 CELL NA	ME: A533 oil pump assemb	lyMACHINE / STAGE:- Manua	al torq	uing n	nachi	ne		OPE	OPERATION: Manual torque checking							
KAIZEN THEME: To impro	ve 5s and operation fat	igue														
WIDELY/DEEPLY: Widely	IDEA:- In A533 manual t															
PRESENT STATUS:- No par	rticular location to	COUNTERMEASURE:-Tr	rav is i	rovic	404 t	to kee	n the			IMAR	K	01No	١.			
keep the flushing jobs		COUNTERMEASURE:- Tray is provided to keep the flushing jobs in manual torquing station-2							ARGE			00				
Recp the hashing jobs									N STAI		18.02	2.2018				
	CO TENERS TO BE SHOWN			EN LON			NI COL	K G	evin Ganes	h	1BERS:					
								BENEFITS:								
						1			-To prevent Customer Complaint							
									-easy to operation -5s improved							
	BEFORE						AFTER			<u> </u>						
WHY - WHY ANALYSIS :- Why1:-Unnecessary man movement Why2:-More distance in input material area Why3:-Material should be in location		RESULT:- Strengthene	d Pro	cess	5.											
Why4:- Tray to be provide										COST INCURRED FOR MAKING KAIZEN						
							M	ATERIA IN F	AL COST RS	LABOUF		H	TOTAL COST IN RS			
									00		00			00		
								sc	OPE 8	& PLA	N FOR HO	RIZONT/	AL DEPL	OYMENT.		
ROOT CAUSE:-:-									CE	ELL	TARGET	ARGET RESP.		STATUS		
REGISTRATION NO. P14/K	K/2018/018															
REGISTERED BY: Ganesh									SCOPE & PLAN FOR HD FOR OTHER PLANTS							

MANAGER'S SIGN: Dinesh