AD▼IK	SOC Improvement Kaizen															P14			
	TPM CIRCLE NO:			ACTIVITY	KK	QM	ΡN	JH IV	SHE	OT	DM	E&T		ZNI IF					
	TPM CIRCLE NAME:		LOSS NO. / STEP						_				MAILI	IN IL	JEAO	ΠΕΓΙ			
0511. 4522	DEPT: Production		RESULT AREA		P	P Q		DEF :- A		D	D S M F		F/IMS	/IMS/05					
KAIZEN THEME : To e	eliminate SOC @ f	ge.	HINE / STAGE: ASSen	OP	KATIC	JN: FI	usning												
WIDELY/DEEPLY:			IDEA	• Oil draining syste	m at	flushi	ng	stage											
<b>PRESENT STATUS:</b> Oil getting spillage after											BENCHMARK						_		
fluching of the component			COUNTERIVIEASURE : Provided a tray to keep								TARGET								
			flushed oil pump for draining all oil into flushing									KAIZEN START 01.11.17							
			station only.									KAIZEN FINISH 03.11.17					_		
												TEAM MEMBERS:							
					r	Mr. Chamraj BT,													
												Mr. Bharadwaj.							
												BENEFITS							
												1. Oil Spillage reduced.							
												TAL NOT AN AND AND AND AND AND AND AND AND AND							KAIZEN SUSTENANCE
			AFTER							R WHAT TO DO : Keep flushed component									
												into tray provided for it. HOW TO DO : Manually. FREQUENCY : 100% after flushing stage.							
			WHY - WHY ANALYSIS :- Why1: Oil getting spillage after flushing of the			RESULT:-													
component.																			
Why2: After flushing operator keeps component																			
directly in output bin for inspection.																			
Why3: No oil draining	g system at flushing	g stage.				Ĭ	C	Y.		0	OST	INCU	RRED F	OR M	AKING	KAIZEN	I.		
				0						MA	TERIA	L COS	T LABOL	IR COST	тот	AL COST			
ROOT CAUSE:- No oil draining system at												RS	IN	RS		IN RS			
flushing stage.			$\mathbf{v}$	INR 120/- INR 120/-															
												SCOPE & PLAN FOR HORIZONTAL DEPLOYME							
REGISTRATION NO. & DATE:1936 & 12.11.17			Oil Spillage after No Oil Spillage after							CE	<b>u</b>	TARGET	R	SP.	STATU	5			
REGISTERED BY: Mr. Manash KP			flushing stage.							No Scope in P14									
MANIACER'S SIGNIA Mar Margar Kumar Davi			nusning stage. flushing stage.									No Scope in P14							

MANAGER'S SIGN: Mr. Manas Kumar Dey