		TPM CIRCLE NO :-	1	ACTIVITY	KK	QM	PM	JH	SHE	отрм	DM	E & T				
	<b>AD▼</b> IK	TPM CIRCLE NAME :		LOSS NO./STEP										ZEN IDEA HEET		
	Plant : P14	DEPT :	Prod	RESULT AREA	с	Q	Р	Р, С	S	М, D	P, C	м				
CELL :	A545	CELL NAME :	Plunger Broaching M/C Axisco STAGE: m/c.						Broacl	operation			:Broac	hing		
KAIZEN THEME :		KAIZEN IDEA :														
To avoid hand damage @ plunger		Burr exit unit is in open condition.								BENCHMARK:						
broaching	stage.									TARGET:    KAIZEN START: 03.1.18						
	BLEM PRESENT STATUS :	COUNTERMEASURE:							TARGET DATE:04.1.18							
	may happen cause of hand	Provided a sheet metal cover at burr exit unit to avoid hand injury.							KAIZEN FINISH: 04.1.18							
get damag	e during cleaning time.								TEAM MEMBERS: Mr. Murali MN							
										Mr. Praveen Jannu						
											BENEFITS:-					
											Safe Working condition , & User					
											friendly.					
	WHY-WHY ANALYSIS:	BEFORE AFTER					KAIZEN SUSTAINANCE									
Why1:- Pro	bability may happen cause							WHAT TO DO:								
of hand ge	t damage during cleaning								Ir reversible Kaizen.							
time.									HOW TO DO:							
Why2:- Bu	urr exit unit is in open															
condition.	-								FREQUENCY:							
									On	One time activity.						
									9	SCOPE & PLAN FOR HORIZONTAL						
										DEPLOYMENT						
									SR. NO	CELL/		трс	RESP.	STATUS		
										PRODU	СТ			011100		
	ROOT CAUSE	RESULTS:							·			· ·				
Burr exit unit is in open condition.																
					-											
									HD SCOPE INFORMATION IN OTHER PLANT							
REGISTRATIC	<b>DN NO.:</b> P14/KK/2018/011		-													
DATE:	28.1.18								SR.N	O. PLA		VHEN	мном	STATUS		
REGISTERE	D BY: Mr. Praveen Jannu		nsafe working	g Safe Wor	king				1	Al	I 25	5.2.18	Prod	Open		
MANAGER	SIGN: Mr. Manas Kumar Dey		condition.	conditio	-											
AHPL/QMS/	FR/09/E, Rev. No.:03, Rev. Date:2	3.01.2018														

AHPL/QMS/FR/09/E, Rev. No.:03, Rev. Date:23.01.2018